

BLACK SHELD CHECK LIST (as of 14 Jul 67)

Page 2

H-Minus	ACT	DOI	RESP INDV	TIME DUE(Z)	TIME DUE(L)	TIME DONE(L)	DONE BY (Initials)
-10:00	Send [redacted] (Terminal wx fcsts)	B-5	CAPT HCC	18/1630	20/0130	0035	[initials]
-9:00	Rev [redacted] (GO-NO GO wx fcsts)	B-11	CAPT HCC	1730	0230	0143	[initials]
-9:00	Give [redacted] input to Msn Coord	B-23	CAPT HCC	1730	0230	0030	[initials]
-8:00	Send [redacted] (thru L-hr, if reqd)	B-16	CAPT HCC	1830	0330	—	—
	Annotate tanker DD Forms 175	B-24	LT Y			0515	JY
25X1	Brief tankers [redacted]	B-24	LT Y	2125	0625	0625	JY
-4:00	Send [redacted] (Terminal wx fcsts)	B-5	LT Y	2230	0730	0722	JY
-4:00	Send [redacted] (Met Watch obs)	B-18	SSGT HAYES	2230	0730	0722	RH
25X1	Brief tankers [redacted]	B-24	LT Y	2250	0750	0800	JY
-3:30	Brief pilots and ops staff	B-20	MAJ B	2300	0800	0800	DEB
25X1	Brief tankers [redacted]	B-24	LT Y	2310	0810	0800	JY
-3:00	Rev [redacted] Amend (GO/NO GO fcsts)	B-11	MAJ B	2330	0830	0746	DEB
-3:00	Rcv Letdown Plates from DCO	B-14	MAJ B	2330	0830	0830	DEB
-3:00	Enter fcsts on Letdown Plates	B-14	MAJ B	2330	0830	0930	JY
-2:30	Msn Obsvr to CP; posts data	B-13	SSGT HAYES	0000	0900	0850	JN
-2:00	Rev [redacted] (Wx Scout reports)	B-22	MAJ B	20/0030	20/0930	0927	DEB
	Pick up APT pictures	B-10	LT Y	0000 or ASAP	0900 or ASAP		
-1:40	Msn Fcstr to CP; Obsvr to wx str	B-13	MAJ B	0050	0950	0950	DEB
-1:35	Letdown plate fcsts to pilots (Notify Mission Coordinator)	B-14	MAJ B	0055	0955	0940	DEB
-1:30	Notify DCOL (If need to rebrief pilots)	B-20	MAJ B	0100	1000	—	—
-1:10	Rebrief pilots if necessary	B-20	MAJ B	0120	1020	—	—
L-Plus	Landing time: 20/0800Z 20/1000Z L						
+0:15	Return Met Watch to wx station	B-13	SSGT HAYES	0742	1642	1630	DEB
+0:15	Start debriefing form	B-15	MAJ B	0742	1642	1635	DEB
+0:45	Attend pilot debriefing	B-15	MAJ B	0845	1745	1715	DEB
ASAP	Give R-118 input to DCOM Coord after debriefing	B-15	MAJ B	ASAP	ASAP	1730	DEB
+24:00	Turn in Msn Wx File to Intell	B-17	MAJ B	22/0729	22/0029	24/1010	DEB

BLACK SHIELD CHECK LIST
(As of 14 Jul 67; with tankers)

Code Name BLACK SHIELD Mission Nr BX6710 Date 20 Jul 67 H-hour 20/0200Z 20/1130L

Msn Pilot A Fcstr Duty Hours 18/10-18I; 20/06-18I
Spare Pilot B Fcstr Duty Hours 19/18-20/0300I
Chase Pilot C Fcstr Duty Hours 20/03-13I

Msn Coord A Obsvr Duty Hours 18/10-18I; 20/07-17I
Msn DCOM B Obsvr Duty Hours 19/18-20/03I
Msn TTFC C Obsvr Duty Hours 20/03I-11I

H-Minus	ACTION	DCI	RESP INDV	TIME DUE(Z)	TIME DUE(L)	TIME DONE(L)	DONE BY (Initials)
-24:00	Start this check list	B-3	MAJ B	19/1230	19/1130	1130	VB
-24:00	Arrange work schedule	B-4	MAJ B	0230	1130	1130	DB
-23:30	Attend Commander's Briefing	B-1	MAJ B	0430	1330	1335	JY
-23:00	Rev <u> </u> (Prelim Ops Data)	B-1	MAJ B	0300	1200	0605	JY
-22:30	Coordinate TTFC support	B-2	MAJ B	0330	1230	0930	JY
	Give prelim data to TTFC <u> </u>	B-2	MAJ B	0300	1200	1300	Not Required JY
-21:00	Rev <u> </u> (Tmnl fcsts)	B-5	MAJ B	0530	1430	1326	JH
-21:00	Start Met Watch on wall map	B-21	MAJ B	0530	1430	1431	JY
-21:00	Rev <u> </u> (Mission wx data)	B-6	MAJ B	0530	1430	1322	JY
	Pick up APT pictures	B-10	MAJ B	0530	1430	1000	JY
	Rev <u> </u> (Composite rte data)	B-6	MAJ B	Vrbl	Vrbl	1713	JH
-17:30	Rev <u> </u> (Mission wx)	B-6	MAJ B	0900	1800	1909	JL
-17:15	Rev <u> </u> (Tmnl fcsts)	B-5	MAJ B	0915	1815	1730	DEB
-17:00	Brief pilot and ops staff	B-7	MAJ B	0930	1830	1830	DEB
-14:00	Rev letdown plates from DCOM	B-14	CAPT MCC	1230	2130	1256I	JL
-14:00	Rev <u> </u> (Tanker msn wx fcst)	B-9	CAPT DCL	1230	2130	2055I	JM
	Letdown plates to DCO	B-14	CAPT MCC	1300	2200	2021	JM
	Rev <u> </u> (Final Ops data)	B-8	CAPT MCC	1330	2230	2148	JM